

Oil Field Environmental Incident Summary

Incident: 20141011074515

Date/Time of Notice: 10/11/2014 07:45

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: SHELL CREEK 1-01 SWD

Field Name: PARSHALL

Well File #: 17058

Date Incident: 10/10/2014

Time Incident: 11:00

Facility ID Number:

County: MOUNTRAIL

Twp: 152

Rng: 90

Sec: 1

Qtr: SE SW

Location Description:

Submitted By: Keith Kallberg

Received By:

Contact Person: Keith Kallberg
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pump Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	3	Barrels	3	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Low

Areal Extent:

South of the building 15 ft. x 80 ft. to the berm then west along the berm 3 ft. x 60 ft.

Potential Environmental Impacts:

Low

Action Taken or Planned:

Pump seal was replaced. Vac truck removed the fluid from the skid building. Cleanup crew brought in to scrape and remove the affected material, fresh material will be brought in to replace what was removed.

Wastes Disposal Location: Fluids put back into the SWD and the solids will be taken to Clean Harbors at Sawyer ND.

Agencies Involved:

Updates

Date: 10/13/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a pump leak, remained on location within perimeter diking according to the report. NDIC retains oversight.